

1/11




FIG. 1




FIG. 2

| | | |
|-----------|-----------|----------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | SUBCLASS |
| DRAFTSMAN | | |

2/11




FIG. 3

3/11




FIG. 4

4/11




FIG. 5




FIG. 6

| | | |
|-----------|-----------|----------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | SUBCLASS |
| DRAFTSMAN | | |

5/11




FIG. 7

6/11




FIG. 8A




FIG. 8B

7/11




FIG. 9A




FIG. 9B

8/11




FIG. 10A




FIG. 10B

9/11




FIG. 11A




FIG. 11B

10/11




FIG. 12A




FIG. 12B

| | | |
|-----------|-----------|----------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | SUBCLASS |
| CRAFTSMAN | | |

11/11




FIG. 13